ECS Configuration	on Chang   qu	est		Р	eage 1 of P	ages
CCR No. 98- 00		Date 1/22/98	Rev. —	Request T	ype CCR	
Priority Routine	Urgent	Emergency X	Affected Release	Rel: 2	Change Class	II
Title (description) GSFC Floor Plan						
Documents Affected			Source Nos (RID, Tech Reference	NCR, Action It	tem, EDC CCR, etc.	) or
920-TDG-004 Rev: <u>0</u> 2			NA			
RTM Change	Start New Bas	eline 🗌				
Problem Requirements for fail ov	ver design caused the r	econfiguration of the C	GDAAC floor plans.			
Proposed Solution The attached floor plans Need by COB: 1/23/98	s now reflects the as b	uilt at launch configura	ation for GDAAC		·	
Impact Analysis:	_	_		500 <b>—</b>	M.O. E	7
Organizations Affected:  Procurement  Science Off	BOO	Contracts  Rel. Dev  Subcontrct	ECS Chief Eng Rel. A Sys. Eng	FOS Rel. C Sys Verf _x	M&O ∑ SCDO Arch. ☐	 ភ
Cost:	None 🗌	Small (Not exceeding \$100,000)	Medium	Large (Over \$500,000)		••••••
Schedule:	None	Other				••••••
Additional LOC			Man-Montl	hs		
Materials	<u> </u>					
Originator <u>Tim. Wells</u>	ext. 4021	Timothy E. Wells Signature	Tunth	1 & W	: <u>US 1-22-9</u> Date	<u> </u>
Office M&O	Office Manager	Tom Jaeger Signature	lim to	preg	//22/ Date	195
Disposition	Approved	Approved w/Com	ment For	ward	Disapproved [	
Comments:	^					

CM010C96

ECS CM-NP

ORIGI. AL

Terry Fisther
Signature